Sig Sauer® ROMEOZero
Quick Reference Card

Power ON: Move the sight, or momentarily press either the UP or DN brightness adjustment button

Power OFF: press and hold either the UP or DN brightness adjustment button for 2 seconds.

After 2 minutes of inactivity (no movement), the sight will enter its **power saving mode** and automatically shut off.

Dot will flash 5 times at the highest or lowest brightness settings.

To disable **MOTAC™**(*), press and hold both buttons for 3 seconds. The sight will flash the LED one time to signify MOTAC™ is disabled. To re-enable MOTAC™ simply repeat the process.

* default

Sig Sauer® ROMEOZero
Quick Reference Card

3 MOA Red Dot   6 MOA Red Dot

Select from **8 Daytime brightness settings** using UP or DN buttons

To change the **CR 1632** battery, remove the sight. Install the new battery positive (+) side facing out (down). Reinstall the sight.

Torque mounting screws to 9 in-lbs.

To **raise your point of impact**, use the included .050" Allen wrench to turn the elevation screw clockwise. To lower, turn counter-clockwise.

To **move your point of impact left**, turn the windage screw clockwise. To move right, turn counter-clockwise.

Footprint: Shield RMS-c

Sig Sauer CS: (603) 610-3000   www.sigsauer.com

1 CM