# Sig Sauer® ROMEO3MAX™

Power ON: Move sight (MOTAC™), or press UP or DN button
Power OFF: press UP or DN and hold 2 seconds.
Select **10 Daytime/2 NV brightness settings** using UP or DN
Sight enters **power saving mode** after 2 minutes of inactivity
Dot flashes 5 times at the highest or lowest brightness settings.
To disable **MOTAC™**(*), press both buttons and hold 3 seconds. Sight flashes LED one time to signify MOTAC™ is disabled. Repeat to re-enable MOTAC™.
* default

GENERAL PURPOSE GRID: 1.00"

Layout / Design llando88@gmail.com 2022. Unlimited copy and distribution permitted. **REV 10**

Sig Sauer® ROMEO3MAX™

3 MOA Red Dot   6 MOA Red Dot

CR1632 battery is behind side loading cover. (1.5mm hex)
Install battery positive (+) side up.

Screws (1.5mm hex) move impacts U/DL/R, 1click=1MOA
25 yds: 6 MOA = 1.6" 3 MOA = 0.8"
10 yds: 6 MOA = 0.6" 3 MOA = 0.3"
Footprint: DeltaPoint Pro / Body Aluminum / IPX7 waterproof

   (603) 610-3000   www.sigsauer.com

ZEROING AID GRID: 3 MOA@25 YD=0.79"

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation.