Trijicon® SRO®
Quick Reference Card

Power on: Press either button to turn on. RMR wakes up in automatic mode.

Press both buttons simultaneously for less than 3 seconds and release to enter automatic mode. Press both buttons simultaneously and hold them for 3 seconds **to turn the unit off**.

Press and release the **plus button** to increase brightness and enter manual mode. Press and release the **minus button** to decrease brightness and enter manual mode.

Aiming dot automatically adjusts to ambient lighting after **16.5 hours.**

REVISION 8   1 IN

Trijicon® SRO®
Quick Reference Card

1.0 MOA Dot   2.5 MOA Dot   5.0 MOA Dot

M**anual illumination** control has 8 brightness settings.
Automatic mode covers settings 3-7 depending on ambient light.
Battery is a CR2032 3V DC Lithium. Install negative side "-" facing down.
The aiming dot will become dimmer as the battery gets low.
Turn **Adjustment screws** in the direction to move impacts, 1click=1MOA
25 yds: 1 MOA=0.3" 2.5 MOA = 0.7" 5.0 MOA = 1.3"
10 yds: 1 MOA=0.1" 2.5 MOA = 0.3" 5.0 MOA = 0.5"
Torque Optic Screws until seated, then secure.
Clean with fresh water and clean cloth, not alcohol, TCE or acetone
Footprint: Trijicon RMR
Trijicon Customer Service: www.trijicon.com (800) 338-0563