

MRDS QUICK REFERENCE CARD SERIES



## Holosun EPS/Carry Red MRS

**Power ON:** Shake or press either brightness button

**Power OFF:** Press "+" and "-" together

Press "-" 3 sec, to go from Circle+Dot (\*), to Dot, to Circle

Press "+" 3 sec to go from Automatic(\*) -> Manual -> Lockout

Solar Fail Safe™ provides dual power (solar and internal)

Automatic Brightness dims down to adjust for ambient light


12 brightness settings (4 NV, 8 daylight)

\*default

GENERAL PURPOSE GRID: 1.00"

Layout/Design llando88@gmail.com 2022. Unlimited copy and distribution permitted. **REV 10.1**

## Holosun EPS/Carry Red MRS



Battery is **CR1620 3V**. Reticle blinks if battery is low.

Insert new battery "+" side **DOWN**

**Screws** move center of impact U/D, R/L. 1 Click = 1.5 MOA

**25 yds:** 2 MOA = 0.5" **10 yds:** 2 MOA = 0.2"

Optic screws: T10 6-32x5/16": 15 in-lbs + blue threadlocker

Tray screw : M2x0.4

Clean with lens cleaner, **NO** alcohol or acetone

Footprint: Holosun "K" Series / 7075 T6 AL / IPX8 Certified

[www.holosun.com](http://www.holosun.com) [warranty@holosun.com](mailto:warranty@holosun.com) (909) 594-2888

ZEROING AID GRID: 2 MOA@25 YD±0.52"

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation.

MRDS QUICK REFERENCE CARD SERIES



## Holosun EPS/Carry Red MRS

**Power ON:** Shake or press either brightness button

**Power OFF:** Press "+" and "-" together

Press "-" 3 sec, to go from Circle+Dot (\*), to Dot, to Circle

Press "+" 3 sec to go from Automatic(\*) -> Manual -> Lockout

Solar Fail Safe™ provides dual power (solar and internal)

Automatic Brightness dims down to adjust for ambient light

12 brightness settings (4 NV, 8 daylight)

\*default

GENERAL PURPOSE GRID: 1.00"

Layout/Design llando88@gmail.com 2022. Unlimited copy and distribution permitted. **REV 10.1**

## Holosun EPS/Carry Red MRS



Battery is **CR1620 3V**. Reticle blinks if battery is low.

Insert new battery "+" side **DOWN**

**Screws** move center of impact U/D, R/L. 1 Click = 1.5 MOA

**25 yds:** 2 MOA = 0.5" **10 yds:** 2 MOA = 0.2"

Optic screws: T10 6-32x5/16": 15 in-lbs + blue threadlocker

Tray screw : M2x0.4

Clean with lens cleaner, **NO** alcohol or acetone

Footprint: Holosun "K" Series / 7075 T6 AL / IPX8 Certified

[www.holosun.com](http://www.holosun.com) [warranty@holosun.com](mailto:warranty@holosun.com) (909) 594-2888

ZEROING AID GRID: 2 MOA@25 YD±0.52"

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation.