

## **Holosun 509T-RD**

**Power ON:** Shake sight or press either brightness button **Power OFF:** Press "+" and "-" simultaneously to turn power and motion sensor off (**Shake Awake**<sup>™</sup> (\*) is disabled)

Press "-" 3 sec, to go from Circle+Dot(\*) -> Dot Press "+" 3 sec, to go from Automatic(\*) -> Manual -> Lockout 10 daylight and 2 NV brightness settings.

\*default

Layout / Design llando88@gmail.com 2022. Unlimited copy and distribution permitted. **REV 10** 

1.00"

GRID:

**PURPOSE** 

GENERAL

2 MOA@25 YD=0.52"

GRID

**EROING AID** 

## **Holosun 509T-RD**



Battery is a **CR1632**. Reticle blinks if the battery is low. Insert new battery "+" side **DOWN**.

**Screws** move center of impact U/D, R/L. 1 click = 1 MOA

**25 vds:** 32 MOA = 8.4" 2 MOA = 0.5"

**10 yds:**  $32 \text{ MOA} = 3.4^{"} 2 \text{ MOA} = 0.2^{"}$ 

6-32 T10 Plate screws=15 in-lbs+blue t/l; clamp=20 in lbs

Clean with lens cleaner, **NO** alcohol or acetone

Footprint: 509T+Clamp / Ti / 1 Meter IPX7 waterproof fogproof

www.holosun.com warranty@holosun.com (909) 594-2888

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation

MRDS QUICK REFERENCE CARD SERIES



## **Holosun 509T-RD**

**Power ON:** Shake sight or press either brightness button **Power OFF:** Press "+" and "-" simultaneously to turn power and motion sensor off (**Shake Awake**<sup>™</sup> (\*) is disabled)

Press "-" 3 sec, to go from Circle+Dot(\*) -> Dot Press "+" 3 sec, to go from Automatic(\*) -> Manual -> Lockout 10 daylight and 2 NV brightness settings.

\*default

Layout / Design Ilando88@gmail.com 2022. Unlimited copy and distribution permitted. **REV 10** 

## **Holosun 509T-RD**



Battery is a **CR1632**. Reticle blinks if the battery is low. Insert new battery "+" side **DOWN**.

**Screws** move center of impact U/D, R/L. 1 click = 1 MOA

**25 vds:** 32 MOA = 8.4" 2 MOA = 0.5"

**10 vds:** 32 MOA = 3.4" 2 MOA = 0.2"

6-32 T10 Plate screws=15 in-lbs+blue t/l; clamp=20 in lbs

Clean with lens cleaner, NO alcohol or acetone

Footprint: 509T+Clamp / Ti / 1 Meter IPX7 waterproof fogproof

www.holosun.com warranty@holosun.com (909) 594-2888

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation

2 MOA@25 YD=0.52" EROING AID GRID:

**PURPOSE**