



## **Holosun EPS/Carry Grn 2**

Power ON: Shake or press either brightness button

Power OFF: Press "+" and "-" together

Press "+" 3 sec to go from Automatic(\*) -> Manual -> Lockout

Automatic Brightness dims down to adjust for ambient light 12 brightness settings (4 NV, 8 daylight)
\*default

Layout/Design llando88@gmail.com 2022. Unlimited copy and distribution permitted. REV 10.1

## **Holosun EPS/Carry Grn 2**



— 2 MO

Battery is **CR1620 3V**. Reticle blinks if battery is low. Insert new battery "+" side **DOWN** 

**Screws** move center of impact U/D, R/L. 1 Click = 1.5 MOA

**25** yds: 2 MOA = 0.5" **10** yds: 2 MOA = 0.2"

Optic screws: T10 6-32x5/16": 15 in-lbs + blue threadlocker

Tray screw : M2x0.4

Clean with lens cleaner, NO alcohol or acetone

Footprint: Holosun "K" Series / 7075 T6 AL / IPX8 Certified

www.holosun.com warranty@holosun.com (909) 594-2888

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation.

MRDS QUICK REFERENCE CARD SERIES



1.00

GRID:

**PURPOSE** 

GENERAL

2 MOA@25 YD=0.

GRID:

AID

EROING



## **Holosun EPS/Carry Grn 2**

**Power ON:** Shake or press either brightness button

Power OFF: Press "+" and "-" together

Press "+" 3 sec to go from Automatic(\*) -> Manual -> Lockout

Automatic Brightness dims down to adjust for ambient light 12 brightness settings (4 NV, 8 daylight)
\*default

Layout/Design llando88@gmail.com 2022. Unlimited copy and distribution permitted. REV 10.1

## **Holosun EPS/Carry Grn 2**



2.40

Battery is **CR1620 3V**. Reticle blinks if battery is low. Insert new battery "+" side **DOWN** 

**Screws** move center of impact U/D, R/L. 1 Click = 1.5 MOA

**25 yds:** 2 MOA = 0.5'' **10 yds:** 2 MOA = 0.2''

Optic screws: T10 6-32x5/16": 15 in-lbs + blue threadlocker

Tray screw: M2x0.4

Clean with lens cleaner,  $\boldsymbol{\mathsf{NO}}$  alcohol or acetone

Footprint: Holosun "K" Series / 7075 T6 AL / IPX8 Certified

www.holosun.com warranty@holosun.com (909) 594-2888

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation.

ZEROING AID GRID: 2 MOA@25 YD=0.52"

PURPOSE GRID: 1.00"

GENERAL