

MRDS QUICK REFERENCE CARD SERIES



Holosun EPS-G-MRS

Power ON: Shake or press either brightness button
Power OFF: Press "+" and "-" together
 Press "-" 3 sec, to go from Circle+Dot (*), to Dot, to Circle
 Press "+" 3 sec to go from Automatic(*) -> Manual -> Lockout

Solar Fail Safe™ provides dual power (solar and internal)
 Automatic Brightness dims down to adjust for ambient light
 12 brightness settings (4 NV, 8 daylight)

*default

Layout/Design llando88@gmail.com 2022. Unlimited copy and distribution permitted. **REV 10.2**

GENERAL PURPOSE GRID: 1.00"

Holosun EPS-G-MRS



Battery is **CR1620 3V**. Reticle blinks if battery is low.
 Insert new battery "+" side **DOWN**
Screws move center of impact U/D, R/L. 1 Click = 1.5 MOA
25 yds: 2 MOA = 0.5" **10 yds:** 2 MOA = 0.2"
 Optic screws: T10 6-32x5/16": 15 in-lbs + blue threadlocker
 Tray screw : M2x0.4
 Clean with lens cleaner, **NO** alcohol or acetone
 Footprint: Holosun "K" Series / 7075 T6 AL / IPX8 Certified

www.holosun.com warranty@holosun.com (909) 594-2888

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation.

ZEROING AID GRID: 2 MOA@25 YD±0.52"

MRDS QUICK REFERENCE CARD SERIES



Holosun EPS-G-MRS

Power ON: Shake or press either brightness button
Power OFF: Press "+" and "-" together
 Press "-" 3 sec, to go from Circle+Dot (*), to Dot, to Circle
 Press "+" 3 sec to go from Automatic(*) -> Manual -> Lockout


Solar Fail Safe™ provides dual power (solar and internal)
 Automatic Brightness dims down to adjust for ambient light
 12 brightness settings (4 NV, 8 daylight)

*default

Layout/Design llando88@gmail.com 2022. Unlimited copy and distribution permitted. **REV 10.2**

GENERAL PURPOSE GRID: 1.00"

Holosun EPS-G-MRS



Battery is **CR1620 3V**. Reticle blinks if battery is low.
 Insert new battery "+" side **DOWN**
Screws move center of impact U/D, R/L. 1 Click = 1.5 MOA
25 yds: 2 MOA = 0.5" **10 yds:** 2 MOA = 0.2"
 Optic screws: T10 6-32x5/16": 15 in-lbs + blue threadlocker
 Tray screw : M2x0.4
 Clean with lens cleaner, **NO** alcohol or acetone
 Footprint: Holosun "K" Series / 7075 T6 AL / IPX8 Certified

www.holosun.com warranty@holosun.com (909) 594-2888

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation.

ZEROING AID GRID: 2 MOA@25 YD±0.52"