

## **Holosun EPS/Carry Red MRS**

Power ON: Shake or press either brightness button

**Power OFF**: Press "+" and "-" together

Press "+" 3 sec to go from Automatic(\*) -> Manual -> Lockout Solar Fail Safe<sup>™</sup> provides dual power (solar and internal)

Automatic Brightness dims down to adjust for ambient light 12 brightness settings (4 NV, 8 daylight) \*default

Layout / Design llando88@gmail.com 2022. Unlimited copy and distribution permitted. **REV 10** 

GRID:

**PURPOSE** 

ENERAL

MOA@25 YD=0.

2

GRID:

<del>A</del>

EROING

## **Holosun EPS/Carry Red MRS**



Battery is **CR1620 3V**. Reticle blinks if battery is low.

Insert new battery "+" side **DOWN** 

**Screws** move center of impact U/D, R/L. 1 Click = 1.5 MOA

**25 yds:** 2 MOA = 0.5'' **10 yds:** 2 MOA = 0.2''

Optic screws: T10 6-32x5/16": 15 in-lbs + blue threadlocker

Tray screw: M2x0.4

Clean with lens cleaner, NO alcohol or acetone

Footprint: Holosun "K" Series / 7075 T6 AL / IPX8 Certified www.holosun.com warranty@holosun.com (909) 594-2888

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation

MRDS QUICK REFERENCE CARD SERIES



## **Holosun EPS/Carry Red MRS**

**Power ON:** Shake or press either brightness button


Power OFF: Press "+" and "-" together

Press "+" 3 sec to go from Automatic(\*) -> Manual -> Lockout Solar Fail Safe<sup>™</sup> provides dual power (solar and internal)

Automatic Brightness dims down to adjust for ambient light 12 brightness settings (4 NV, 8 daylight) \*default

Layout / Design Ilando88@gmail.com 2022. Unlimited copy and distribution permitted. **REV 10** 

## **Holosun EPS/Carry Red MRS**



Battery is **CR1620 3V**. Reticle blinks if battery is low. Insert new battery "+" side **DOWN** 

**Screws** move center of impact U/D, R/L. 1 Click = 1.5 MOA

**25 yds:** 2 MOA = 0.5'' **10 yds:** 2 MOA = 0.2''

Optic screws: T10 6-32x5/16": 15 in-lbs + blue threadlocker

Tray screw: M2x0.4

Clean with lens cleaner, NO alcohol or acetone

Footprint: Holosun "K" Series / 7075 T6 AL / IPX8 Certified

warranty@holosun.com (909) 594-2888 www.holosun.com

Instructions: Cut on dotted lines / fold to make a 3x5 "card". Information adapted from OEM sources; not verified nor endorsed. User is advised to verify any content herein with manufacturers documentation

2 MOA@25 YD=0. ZEROING AID GRID:

GRID:

PURPOSE

GENERAL